OT 1 9 2005

we of

**PATENT** 

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: Examiner: Mark Wallerson Yuichi HOSODA, et al. Group Art Unit: 2626 U.S. Patent No.: 6,914,687 B1 Confirmation No.: 9642 Issued: July 5, 2005 Appl. No.: 09/662,134 Filed: September 14, 2000 For: DATA PROCESSING APPARATUS October 19, 2005 AND IMAGE RECORDING APPARATUS, METHOD FOR CONTROLLING DATA PROCESSING APPARATUS AND METHOD FOR CONTROLLING IMAGE RECORDING APPARATUS, AND STORAGE MEDIUM Commissioner for Patents

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

Post Office Box 1450

Alexandria, VA 22313-1450

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

10/20/2005 HLE333 00000106 6914687

01 FC:1811

100.00 QP

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our New York office at the address given below.

Respectfully submitted,

William M. Wannisky Attorney for Patentees Registration No. 28,373

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

WMW\tas

DC\_MAIN 218332v1

# Staple Here Only! Staple Stapl

#### UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO.

6,914,687 B1

DATED

July 5, 2005

INVENTOR(S) :

Yuichi HOSODA, et al.

Page 1 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### ON THE COVER PAGE:

#### IN THE ABSTRACT, ITEM (57):

Line 4, "requested" should read --requesting--.

#### COLUMN 2:

Line 53, "in-this" should read --in this--.

#### COLUMN 3:

Line 2, "occur" should read --occurs--.

#### COLUMN 4:

Line 35, "cross sectional" should read --cross-sectional--.

#### COLUMN 6:

Line 56, "an own" should read --an--; and Line 67, "port" should read --port;--.

#### COLUMN 7:

Line 46, "(now shown)" should read --(not shown)--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

**PATENT NO.** <u>6,914,687</u> B1

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) WMW\tas

#### UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO.

6,914,687 B1

DATED

July 5, 2005

INVENTOR(S) :

Yuichi HOSODA, et al.

Page 2 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 9:

Line 11, "(now shown)" should read --(not shown)--; and Line 32, "(now shown)" should read --(not shown)--.

#### COLUMN 10:

Line 57, "use" should read --user--.

#### COLUMN 16:

Line 30, "described" should read --be described--.

#### COLUMN 17:

Line 36, "bun" should read --bin--.

#### COLUMN 18:

Line 60, "receives to analyze" should read --receives and analyzes--.

#### COLUMN 19:

Line 21, "a" (second occurrence) should read --an--; and Line 45, "Image" should read --image--.

#### COLUMN 21:

Line 30, "convert" should read --converts--; and Line 35, "a" should read --an--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>6,914,687 B1</u>

No. of add'l. copies @ 30¢ per page

 $\Box$ 

Form PTO 1050 (Rev. 3-82) WMW\tas

### UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO.

6,914,687 B1

DATED

July 5, 2005

INVENTOR(S) :

Yuichi HOSODA, et al.

Page 3 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 23:

Line 57, "cross sectional" should read --cross-sectional--.

#### COLUMN 26:

Line 50, "performs" should read --perform--.

#### COLUMN 28:

Line 28, "is" should read --are--; and Line 63, "bid' should read --bit--.

#### COLUMN 29:

Line 30, "an" should read --a--.

#### COLUMN 31:

Line 28, "ROM 404," should read --ROM 404.--.

#### COLUMN 32:

Line 16, "operates" should read --operate--; and Line 32, "is' should be deleted.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 6,914,687 B1

No. of add'l. copies @ 30¢ per page

	_
•	_ \
- 1	

Form PTO 1050 (Rev. 3-82)

WMW\tas

# PRINTER'S TRIM LINE

#### UNITED STATES PATENT AND TRADEMARK OFFICE

### **CERTIFICATE OF CORRECTION**

PATENT NO.

6,914,687 B1

DATED

July 5, 2005

INVENTOR(S) :

Yuichi HOSODA, et al.

Page 4 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 34:

Line 26, "the" (second occurrence) should read --in--;

Line 54, "executes" should read --execute--;

Line 56, "updates" should read --update--; and

Line 58, "are" should read --is--.

#### COLUMN 35:

Line 3, "described" should read --be described--;

Line 54, "job separate" should read --separate job--;

Line 57, "job separate" should read --separate job--;

Line 58, "job separate" should read --separate job--; and

Line 60, "job separate" should read --separate job--.

#### COLUMN 37:

Line 4, "an" should read --a--.

#### COLUMN 39:

Line 6, "so" should read --to--.

#### COLUMN 40:

Line 1, "designates" should read --designate--; and Line 65, "sate," should read --state,--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) WMW\tas

PATENT NO. 6,914,687 B1

No. of add'l. copies @ 30¢ per page

⇒ \_\_

### UNITED STATES PATENT AND TRADEMARK OFFICE

### CERTIFICATE OF CORRECTION

PATENT NO.

6,914,687 B1

**DATED** 

July 5, 2005

INVENTOR(S) :

Yuichi HOSODA, et al.

Page 5 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 45:

Line 25, "a" (first occurrence) should read --an--.

#### COLUMN 49:

Line 44, "jot" should read --job--.

#### COLUMN 50:

Line 2, "include" should read --includes--.

#### COLUMN 51:

Line 2, "include" should read --includes--; and

Line 4, "port" should read --ports--.

#### COLUMN 52:

Line 16, "include" should read --includes--;

Line 23, "method" should read --methods--;

Line 24, "each" should read -- from each--;

Line 35, "include" should read --includes--;

Line 46, "each" should read -- from each--; and

Line 60, "an" (second occurrence) should be deleted.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) WMW\tas

**PATENT NO.** <u>6,914,687</u> B1

No. of add'l. copies @ 30¢ per page

⊏>

#### UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO.

6,914,687 B1

**DATED** 

July 5, 2005

INVENTOR(S) :

Yuichi HOSODA, et al.

Page 6 of 6

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### COLUMN 53:

Line 22, "include" should read --includes--;

Line 28, "method" should read --methods--;

Line 30, "each" should read -- from each--; and

Line 40, "include" should read --includes--.

#### COLUMN 54:

Line 8, "each" should read -- from each--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,914,687 B1

No. of add'l. copies @ 30¢ per page

 $\Box$ 

Form PTO 1050 (Rev. 3-82) WMW\tas